## Appendix 1: Summary of Carey's Gully Complex POM data

Event	Date & time	Locations	Average temp ( <sup>0</sup> C)	Average wind speed (kn)	Wind direction	Odour detected	Observations	Comments
1	11 Mar 04 18:00 – 20:00	Mitchell St	15	4	SW	Compost	On-site: o/o confirmed x 7	Dilution of odour leaving the site in light SW winds
	18.00 - 20.00	CG Bund	14	3.6	Swirling Catchment: Light SW winds	Compost/musty	Catchment: odours, not o/o Complaints: None	
2	5 April 04 18:40 – 20:30	Mitchell St	7-14	0 - 2	NW	None	On-site: o/o confirmed x 5. Catchment: No odours Complaints: None	the site LEL doors open, potential link to sewage odour detected on the bund Early complaints from Kowhai Park, later ones from Kingston POM monitoring station at Happy Valley, but
	18:40 – 20:30	CG Bund	7 – 12	0 - 3	Swirling	Biofilter, stockpiles (vegetation), biofilter (UWI), active face, sewer odour		
3	13 April 04 19:00 – 21:00	Domanski Cres	5.5 - 12	0.1 – 4.5	NE	Active face, stockpiles (compost), sewer odour	On-site: odours, not o/o Catchment: odours, not o/o Complaints: 8 from 5 - 8.45pm	
		CG Bund	7 - 10	0 - 3	S	UWI Clarifer		
4	14 April 04 19:30 – 21:30	Quebec St	9.8 – 13.9	0.5 – 2.3	NW/Swirling	Stockpiles (vegetation)	On-site: odours, not o/o	Light winds moving odour off site
		CG Gate	12.5 – 13.8	1.1 – 2.3	NW/swirling	Fermented, Stockpiles (vegetation)	Catchment: odours, not o/o	
							Complaints: None	

o/o - offensive and/or objectionable odour

UWI - United Water International Limited

LEL - Living Earth Limited

CG - Carey's Gully

Event	Date & time	Locations	Average temp ( <sup>0</sup> C)	Average wind speed (kn)	Wind direction	Odour detected	Observations	Comments
5	26 April 04	Monteith St	11.5 - 12.4	1.5 - 4	S	Compost/musty	On-site: o/o confirmed x 6	o/o confirmed both on-site and in the catchment
	17:30 – 19:30	CG Bund	9.7 – 14.3	1.5 – 4.6	S	Varied (Ammonia, sewer, dirty linen like, sewer, sulphidic)	Catchment: o/o confirmed x 1 Complaints: 10	Four complaints received during the monitoring period
6	10 May 04 15:30 – 17:00	Monteith St	10.5 - 14	2.5 – 9	SE	Sewer, stockpiles, compost	On-site: o/o confirmed x 3	Dilution of odours leaving the site
		CG Bund	11.2 – 14.5	0.5 - 8	S	Sewer, stockpiles, compost, active face	Catchment: odours, not o/o Complaints: None	Light winds moving odour off site
7	19 May 04	Mitchell St	15.1 – 26.9	0 - 5	E	Stockpiles	On-site: odours, not o/o Catchment: odours, not o/o Complaints: None	Light winds moving odour off site
	09:30 – 12:00	CG Bund	14 -20	0 - 4	E/SW	Stockpiles		
8	19 May 04	Monteith St	14.7	0 – 1.5	E	No odour	On-site: None	
	18:30 – 20:30	CG Bund	13.9 - 16	0	E	No odour	Catchment: None Complaints: None	
9	20 May 04	Mitchell St	14.7 – 15	0	0	No odour	On-site: o/o	Complaints from Kingston, Happy Valley during monitoring
	18:40 – 21:00	CG Bund	10.2 – 11.7	0 – 3.5	NNE	Stockpiles, Biofilter (UWI), deodoriser	<ul> <li>confirmed x 3</li> <li>Catchment: None</li> <li>Complaints: 3</li> </ul>	

Event	Date & time	Locations	Average temp ( <sup>0</sup> C)	Average wind speed (kn)	Wind direction	Odour detected	Observations	Comments
10	9 June 04 17:00 – 19:00	Mitchell St	13.8 – 14.2	0	S	Stockpiles	On-site: o/o	LEL doors open on arrival. Complaints tailed off soon after doors were shut Noticed that when deodorisers went off at 18:30 the odour became more intense and more constant
		Quebec St	7	0	Swirling	Sludge bins, stockpiles, deoderiser	<ul> <li>confirmed x 5</li> <li>Catchment: odours, not o/o</li> <li>Complaints: 5</li> </ul>	
		CG Bund	3.8 - 8.8	0 – 1.6	Swirling	Sludge bins, stockpiles,		
11	10 June 04	Domanski Cres	11 - 15	1 - 2	N/NW	No odour	On-site: o/o confirmed x 2 Catchment: None Complaints: 3	Dilution of odours leaving the site
	09:00 – 11:00	CG Gate	9.2 - 14	0.1 - 5	N	Stockpiles, Active face, Sewage,		
12	2 Feb 05	Domanski Cres	18 – 26.5	0 - 3.4	S/NE	No odour	On-site: None	Clear night after a hot day
	21:00 – 22:30	CG Gate	19.7 – 22.9	0 – 3.6	SE/NW	No odour	Catchment: None Complaints: 2	Monitoring at these locations to characterise any katabatic air flow effect
13	3 March 05 17:30 – 19:30	Mitchell St	15 – 21	0 – 3.5	S	Biofilter, Active face	On-site: odours, not o/o	Officer near complainant site at time of complaint
		CG Bund	15.1 - 22	0.1 6.8	S/SW	Stockpiles (compost), Sewer odour	Catchment: odours, not o/o Complaints: 7	from 2 complainants - no odour detected. Complainant validity suspect

Event	Date & time	Locations	Average temp ( <sup>0</sup> C)	Average wind speed (kn)	Wind direction	Odour detected	Observations	Comments
14	16 March 05 09:15 – 11:15	Mitchell St	18.6 – 25.4	0 – 4.8	SW	Stockpiles, biofilter (LEL), sewer, active face	On-site: odours, not o/o Catchment: None	Level 3 sludge odour detected on Bund when LEL doors open
		CG Bund	19.1 – 25.5	0 – 1.1	SW	Biofilter (UWI), stockpiles, active face, sewer	Complaints: 7 earlier in morning	Compost smell correlated with turning of stockpiles by UWI

## Appendix 2: Summary of Taylor Preston POM data

Event	Date & Time	Locations	Average temp ( <sup>0</sup> C)	Average wind speed (kn)	Wind direction	Odour detected	Observations	Comments
1	01 Dec 04 08:40 – 10:40	Gurkha Crescent	18.5	5.7	N	Rendering, wet wool (stockyards) and burnt odours (dryer). Some distinct low level asphalt odour.	On-site: No o/o odour confirmed Catchment: No o/o odour confirmed Complaints: x 1	Works Infrastructure asphalt plant was operating during the investigation, some odour detected from them.
		Maldive Street	24.3	3.6	Swirling	Stockyards		
2	8 Dec 04 14:15 – 16:15	Gurkha Crescent	26.0	1.4	NNE	Rendering odours on occasions, with some stockyards (see observations) and some light burnt odours (dryer)	On-site: No o/o odour confirmed Catchment: No o/o odour confirmed Complaints: x 1	Sheep in paddock at the bottom of Maldive Street, hence may have detect some odour form them.
		Maldive Street	20.5	1.2	Swirling	Not a lot of odour detected at either site for the conditions, just the occasional wave of stockyard odour		

/o - offensive and/or objectionable odour

Event	Date & Time	Locations	Average temp ( <sup>0</sup> C)	Average wind speed (kn)	Wind direction	Odour detected	Observations	Comments
3	13 Dec 04 8:55 – 10:55	Gurkha Crescent	20.7	2.2	N	Waves of stockyard odours (wet wool, faecal)	On-site: No o/o odour confirmed Catchment: No o/o	Sheep yards were quite full during the investigation. This probably accounts for the stockyards odours that were detected during the investigation.
		Maldive Street	22.3	1.7	S	Not much odour detected at this site, some stockyard type odours	odour confirmed Complaints: None	
4	7 Feb 05 14:40 – 16:40	Gurkha Crescent	21.0	17.1	N	Rendering odours detected, burnt odours (dryer) and a range of odours emanating form the stockyards area (wet wool etc)	On-site: No o/o odour confirmed Catchment: No o/o odour confirmed Complaints: x 5	Gurkha Crescent during monitoring period, resulted in
		Maldive Street	24.3	2.4	S	No odour detected at this location		